

AUG - 1 REC'D

OAKLAND, CALIF.

TO: Service Departments

FROM: Walter E. Kaelin, V.P. Engineering


DATE: July 26, 1977


SUBJECT: 1) V-108 A7 Oscillator Board


2) V-101 Schematic, Components Location


- 1) We recently changed the oscillator board of the V108 (and V107) transceiver from mechanical to diode channel switching. This results in improved operation as well as less effort required to rotate the switch. Enclosed is the new schematic and component location for servicing.
- 2) We still receive quite a few calls for schematics on the V101 handheld VHF transceiver. So many in fact, that we have reprinted the schematic and components location. A copy is attached for your service department files.

sovice file










V-108, A7 Board P/N 9115 7308 Rev. A 7/21/77



Transfer and the same of the party of the pa

194 1 . - 11

